



August 2021 Elementary Playground Review

<u>Elementary School Building</u>	<u>Number of Students*</u>	<u>Playground Manufacturer</u>	<u>Year Installed/Updated</u>	<u>Playground Description</u>	<u>Playground Age Range</u>	<u>Current Estimated Condition**</u>	<u>Inspection Report</u>	<u>Comments</u>
Bower	409	Navistar	2005	1 Structure & Swings	K-5, Special Needs	3	Bower Playground Inspection Report	Zero Priority 1 Issues on all structures
Bower		Nutoys	1980	1 Structure & Swings	K-5	1		
Bower		Playworld	1997	1 Structure & Bars	K-5	2		
Emerson	272	Nutoys	2002	1 Structure & Swings	K-2	3	Emerson Playground Inspection Report	Zero Priority 1 Issues on all structures
Emerson		Nutoys	1997	1 Structure & Swings	K-5	2		
Hawthorne	172	Nutoys	1987-2009	1 Structure, Bars, Swings, Climber & Funnel	K-5	2	Hawthorne Playground Inspection Report	Zero Priority 1 Issues
Jefferson Early Childhood Center	275	Nutoys	2020	2 Structures	Pre-K	4		No Report was generated based on Installation Year (2020)
Johnson	452	Landscape Structures	1990-2006	2 Structures & Bars	K-5	1	Johnson Playground Inspection Report	Zero Priority 1 Issues - Identified as top priority for replacement along with Lincoln
Johnson			1990	Bars & Climber	K-5	1		
Johnson		Landscape Structures	1997	2 Structures & Swings	K-5	1		
Lincoln	444	Miracle	1993	1 Structure & Bars	K-2	1	Lincoln Playground Inspection Report	Five Priority Issues were Identified and Rectified in July 2021. Identified as top priority for replacement along with Johnson
Lincoln		Miracle	1985-1991	1 Structure, Bars & Swings	K-5	1		
Longfellow	336	Nutoys	2001	1 Structure, Bars & Swings	K-5	3	Longfellow Playground Inspection Report	Zero Priority 1 & 2 Issues
Lowell	266	Landscape Structures	1996	1 Structure & Swings	K-5	2	Lowell Playground Inspection Report	Zero Priority 1 Issues on all structures
Lowell		Nutoys	1994	1 Structure, Playboard & Funnel	K-5	2		
Madison	413	Miracle	2004	1 Structure	K-2	3	Madison Playground Inspection Report	Zero Priority 1 Issues on all structures
Madison		Miracle	2001	1 Structure & Bars	K-5	3		
Madison		Miracle	2020	2 Structures, Bars & Swings	K-5	4		
Pleasant Hill	544	Nutoys	1996	1 Structure	K-2	2	Pleasant Hill Playground Inspection Report	Only one (Priority 4) Issue noted. All other conditions assessed as compliant.
Sandburg	388	Nutoys	1996	2 Structures, Bars & Swings	K-5	2	Sandburg Playground Inspection Report	Zero Priority 1 Issues on all structures
Sandburg		Nutoys	1994	1 Structure, Bars & Swings	K-5	2		
Sandburg		Nutoys	1998	2 Structures, Bars & Swings	K-5	2		
Washington	362	Miracle	2004	1 Structure, Bars & Swings	K-5	3	Washington Playground Inspection Report	Zero Priority 1 Issues
Whittier	410		1998	1 Structure & Bars	K-5	2	Whittier Playground Inspection Report	Zero Priority 1 Issues
Wiesbrook	476	Landscape Structures	1996	1 Structure & Swings	K-2	2	Wiesbrook Playground Inspection Report	Zero Priority 1 Issues on all structures
Wiesbrook		Landscape Structures	1997	2 Structures & 2 Swings	K-5	2		
* As of Friday, August 6, 2021								
** Condition 1 = Poor Condition - System will need significant repair or replacement in 1-3 Years								
** Condition 2 = Fair Condition - System will probably require repair or replacement anytime within 4-8 Years								
** Condition 3 = Good Condition - System is functionally consistent with original purpose but may show signs or normal wear, tear and deterioration. Reassess every 5 years								
** Condition 4 = Excellent Condition - Built within last 5 years. Reassess every 5 years								